ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
2

Ward Name
Chowdeshwari Ward

Street ID
W0334, W0453, W0451, W0439, W0427, W0435, W0340, W

Street Name
R H B Colcny, 5th Crs, 6th Crs, NA, Mariyappa Lyt, R H B Colcny, 7th Crs

Significant Landmark
Manavarthi Thoto Cross Roads

Segment No.
2/C-W0334/S102656

Total Length (m)
179.16

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	44.94	77.594044	13.106222	77.593704	13.106207	W0342	W0427
2	134.22	77.594072	13.106381	77.595227	13.106141	W0434	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of CC road at Manavarthi Thoto Cross Roads near Anjeneyalu House and CC drain at Markandeya Temple in Ward no 02 of Yelahanka Sub-Divisio

Sanctioned Estimated Amount (Rs.)
1300000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Road

Other Work Type

Tender
Not a Tender

Work Details
Construction of CC road at Manavarthi Thoto Cross Roads near Anjeneyalu House and CC drain at Markandeya Temple in Ward no 02 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
002-16-000034

Work Order No.
BBMP/EE (YNK.D)/WO/61/2016-17

Work Order Date
30/04/2016

Period of Extention
90 DAYS

Defect Liability Period From
29/12/2016

Defect Liability Period To
28/12/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

9449863065

Field Inspection Details

Number of Trees

2

Any Other Information

Name

RAMANANJEEVAIAH

Date of Inspection

24/02/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** W0334, W0453, W0451, W0439,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/02/2017	26/03/2017	COMPLETED
SE	VASU K M	24/02/2017	26/03/2017	COMPLETED
EE	VASU K M	24/02/2017	26/03/2017	COMPLETED
AEE	G.B. PRABHAKAR	24/02/2017	26/03/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** W0334, W0453, W0451, W0439,